









PZ2/1x5...7
1,6...1,8 Nm

Hex 4
5 Nm



2x $\varnothing$ 25



PZ2/1x5...7
1,8...2,0 Nm



3x 



OFF O



View: General installation and life-cycle manual available at
www.katko.com/terms-conditions